


## Flexible current clamps

### PAN 3000A+

Flexible digital clamp meter 3000 A AC True RMS with automatic function selection

- Digital Display 21 mm
- **Backlight**
- **True RMS measurement**
- Auto range
- Data-Hold
- **LED flashlight**
- Auto power off

**Scope of delivery:** protective cover, test leads, Operating manual



Technical Data	PAN 3000A+
DC voltage (V=)	1 mV - 600 V
AC voltage (V~)	1 mV - 600 V
AC current (A~)	10 mA - 3000 A
Resistance ( $\Omega$ )	1 $\Omega$ - 6 M $\Omega$
Continuity test (•)))	< 50 $\Omega$
Frequency (Hz)	0,1 Hz - 10 kHz
Jaw opening $\emptyset$	160 mm
Weight (gross / net)	503 / 204 g
Dimensions	176 x 335 x 30 mm
Required battery(s):	3 x 1,5 V AAA
Measuring category (CAT)	CAT IV 600 V
Accuracy (%)	0,5 % - 3 %



PAN 3000A+ Video DE:



PAN 3000A+ Video EN:

